

Table 1
Damaged Asbestos-Containing Materials Inventory

Material Description	Material Location	Response Action	Estimated Quantity	Tentative Abatement Date	Preparation Needed	Room Ready for Abatement	Abatement Complete	Notes
Significantly damaged skim coat plaster	Entry ceiling, one spot near janitor's hallway, and one spot near entrance	1,3	10 SF	WO 1/29				
Significantly damaged skim coat plaster	3 rd floor hall ceiling near balcony entrance	3	10 SF	WO 1/29				
Damaged skim coat plaster	Room 111. One spot near radiator and scattered spots above drop ceiling	1,2	5 SF	WO 1/29				
Damaged skim coat plaster	Room 166. One damaged spot on ceiling	2	3 SF	WO 1/29				
Damaged skim coat plaster	Room 166A. One damaged spot on ceiling	2	3 SF	WO 1/29				
Damaged paint	Room 171, Peeling paint on ceiling in 3 spots	4	300 SF	WO 1/29				
Significantly damaged skim coat plaster	Room 210. One spot near door	3	2 SF	WO 1/22				
Damaged paint	Room 210 ceiling throughout and above drop ceiling	1,4	1,500 SF	WO 1/22				
Damaged skim coat plaster	Room 211 and office. Two spots near radiator and two spots near doors	2	5 SF	WO 1/22				
Damaged paint	Room 211 office ceiling throughout	4	400 SF	WO 1/22				
Damaged skim coat plaster	Room 215. One spot near on ceiling above drop ceiling. Two spots on west wall plaster	1,2	5 SF	WO 1/22				

Material Description	Material Location	Response Action	Estimated Quantity	Tentative Abatement Date	Preparation Needed	Room Ready for Abatement	Abatement Complete	Notes
Damaged skim coat plaster	Headmaster. One spot near radiator	2	2 SF	WO 1/22				
Significantly damaged skim coat plaster	Room 222A and 222B. 2 spots on ceiling near window wall and two spots on wall plaster	3	15 SF	WO 1/15				
Significantly damaged skim plaster	Room 226A. One spot on ceiling above drop ceiling	1,3	3 SF	WO 1/15				
Damaged skim coat plaster	Room 240. One spot in bathroom wall	2	3 SF	WO 1/15				
Damaged skim coat plaster	Room 243. Multiple spots near windows	2	10 SF	WO 1/15				Xmas week?
Significantly damaged skim coat plaster	Room 250. One big spot near radiator and other spots throughout the covered walls. One spot on ceiling	3	30 SF	WO 1/15				
Damaged paint	Room 250. Ceiling throughout	4	1,600 SF	WO 1/15				
Significantly damaged skim coat plaster	Room 251. One spot on window wall and one spot on ceiling	3	10 SF	12/11-12/12				
Damaged paint	Room 251. Ceiling throughout	4	1,600 SF	12/11-12/12				
Significantly damaged skim coat plaster	Room 252. Three spots on window wall. One spot on ceiling near windows	3	15 SF	12/12				
Damaged skim coat plaster	Room 253. One spot on window wall. And one spot on ceiling near windows	2	3 SF	12/12				
Damaged paint	Room 253. One spot on ceiling	4	10 SF	12/12				

Material Description	Material Location	Response Action	Estimated Quantity	Tentative Abatement Date	Preparation Needed	Room Ready for Abatement	Abatement Complete	Notes
Significantly damaged skim coat plaster	Room 254. One large whole in window wall	3	10 SF	12/14				
Damaged paint	Room 254. One spot on ceiling	4	10 SF	12/14				
Damaged paint	Room 255. Plaster ceiling above drop ceiling	1,4	800 SF	12/13				
Damaged skim coat plaster	Room 255. One spot on window wall.	2	10 SF	12/13				
Damaged skim coat plaster	Room 256. One spot on window wall. And one spot on ceiling near windows	2	10 SF	12/14				
Damaged skim coat plaster	Room 257. Two spots on window wall and one spot on north wall. Spot damaged ceiling plaster above drop ceiling	1,2	20 SF	12/15				
Significantly damaged skim coat plaster	Room 258. One spot near window wall, one spot on the north wall and one spot near ceiling	3	20 SF	12/15				
Damaged skim coat plaster	Gus's office (259)	2	1 SF	12/15				
Significantly damaged skim coat plaster	Room 311. One spot near radiator	3	5 SF	W/O 1/2				
Damaged skim coat plaster	Room 312. One spot of damaged plaster near radiator	2	2 SF	W/O 1/2				
Damaged paint	Room 312. Peeling paint one ceiling in multiple areas	4	400 SF	W/O 1/2				
Damaged paint	Room 313 Peeling paint	1,4	400 SF	W/O 1/2				

Material Description	Material Location	Response Action	Estimated Quantity	Tentative Abatement Date	Preparation Needed	Room Ready for Abatement	Abatement Complete	Notes
	throughout ceiling area above drop ceiling							
Damaged skim coat plaster	Room 314. One spot damaged plaster on wall and one spot on ceiling	2	5 SF	W/O 1/2				
Damaged paint	Room 314. Paint peeling on ceiling throughout	4	1,200 SF	W/O 1/2				
Damaged skim coat plaster	Room 315. One spot near radiator	2	30 SF	12/1	Walls only		12/1	
Damaged paint	Room 315. Peeling paint throughout ceiling	4	1,200 SF	12/1 (begin if runover from 11/30)		NA	12/1	Above drop ceiling – No work
Significantly damaged skim coat plaster	Room 316. 3 Large areas on wall. One spot on ceiling.	3	200 SF	11/28-11/29	Empty	11/28	11/29	
Damaged paint	Room 316. Peeling paint throughout ceiling	4	800 SF	11/28-11/29	Empty	11/28	11/29	
Damaged skim coat plaster	Room 317. One spot near radiator	2	10 SF	11/30	Empty		11/30	
Damaged paint	Room 317. Peeling paint throughout ceiling	4	800 SF	11/30 (begin if runover from 11/29)	Empty		11/30	
Damaged skim coat plaster	Room 321. Two areas of water damaged ceiling plaster and one spot damaged wall plaster	2	10 SF	WO 1/8				
Damaged skim coat plaster	Room 322. Two spots near radiator and window wall	2	5 SF	WO 1/8				
Damaged paint	Room 322. Two spots of peeling paint on ceiling	4	20 SF	WO 1/8				

Material Description	Material Location	Response Action	Estimated Quantity	Tentative Abatement Date	Preparation Needed	Room Ready for Abatement	Abatement Complete	Notes
Damaged skim coat plaster	Room 324. One spot near radiator	2	5 SF	WO 1/8				
Damaged skim coat plaster	Room 325. One damaged spot near radiator, one spot on east wall, and one spot of peeling paint on ceiling	2,4	10 SF	WO 1/8				
Damaged paint	Room 326. Peeling paint on ceiling in one spot	4	20 SF	WO 1/8				
Damaged paint	Room 327. Peeling paint on ceiling in one spot	4	20 SF	WO 1/8				
Significantly damaged skim coat plaster	Room 333. One large spot near radiator and around windows	3	10 SF	WO 12/25				Tentatively scheduled for holiday week
Damaged 9"x9" grey floor tile	Room 333. Near windows	5	8 SF	WO 12/25				Tentatively scheduled for holiday week
Damaged skim coat plaster	Room 334. 6 spots near windows	2	15 SF	WO 12/25				Tentatively scheduled for holiday week
Significantly damaged skim coat plaster	Room 335. 4 spots near windows	3	15 SF	WO 12/25				Tentatively scheduled for holiday week
Damaged skim coat plaster	Room 336. 4 spots near windows	2	10 SF	WO 12/25				Tentatively scheduled for holiday week
Damaged skim coat plaster	Room 337. One spot near window	2	5 SF	WO 12/25				Tentatively scheduled for holiday week
Damaged skim coat plaster	Room 338. One spot near radiator	2	1 SF	WO 12/25				Tentatively scheduled for holiday week
Damaged 9"x9" grey floor tile	Room 330	5	10 SF	12/8	Walls Only			
Significantly damaged skim coat plaster	Room 341. 2 spots on east wall and 1 spot on south wall	3	30 SF	12/6	Empty	12/4		
Peeling paint ceiling	Room 341 throughout	4	1,600 SF	12/6	Empty	12/4		

Material Description	Material Location	Response Action	Estimated Quantity	Tentative Abatement Date	Preparation Needed	Room Ready for Abatement	Abatement Complete	Notes
Significantly damaged skim coat plaster	Room 342. 2 spots on window wall	3	100 SF	12/4-12/5	Empty	12/4		
Peeling paint ceiling	Room 342. One large area	4	800 SF	12/4-12/5	Empty	12/4		
Significantly damaged skim coat plaster	Room 344. One large whole near radiator	3	5 SF	12/8	Walls Only			
Damaged skim coat plaster	Room 345. 2 spots near radiator. one spot on south wall	2	10 SF	12/7	Empty			
Peeling paint ceiling	Room 345 throughout	4	800 SF	12/7	Empty			
Damaged skim coat plaster	Room 345A. One spot near window	2	10 SF	12/7-12/8	Walls Only			
Damaged skim coat plaster	Room 346. 5 spots on east wall, and one spot near radiator	2	10 SF	WO 12/18				
Damaged skim coat plaster	Room 347. One spot near radiator, and one spot on south wall	2	10 SF	WO 12/18				
Peeling paint ceiling	Room 347. One large area	4	300 SF	WO 12/18				
Damaged skim coat plaster	Room 348. One spot near radiator	2	2 SF	WO 12/18				
Damaged skim coat plaster	Room 349. One spot near radiator and one spot on south wall	2	5 SF	WO 12/18				
Damaged skim coat plaster	Room 350. One spot near radiator	2	5 SF	WO 12/18				
Damaged skim coat plaster	Room 351. Peeling paint and damaged throughout ceiling above drop ceiling	1,2	600 SF	WO 12/18				
Damaged skim coat plaster	Room 352. One spot near radiator	2	1 SF	WO 12/18				

SF – square feet

LF – linear feet

Response Actions:

- 1- Restrict access above drop ceiling
- 2- Apply bridging encapsulant to damaged areas
- 3- Apply either sheetrock, joint compound and bridging encapsulant to significantly damaged areas
- 4- Intact peeling paint area with bridging encapsulant
- 5- Replace damaged 9"x9" grey floor tiles with new tiles
- 6- Wet wrap damaged areas

Walls Only – Please remove all posters and anything else that is not permanently attached to the walls for inspection.

Empty – Please clear walls as above and empty room of all movable furniture.

******* ANY EARLY FINISHES – WORKERS CAN BEGIN DOING PAINT STABILIZATION IN THE HALLWAYS NEAR WHERE THEY ARE WORKING FOR THE DAY.**