

Lynn G Haskin

All drinking fountains had none detected

| <b>Date of sample</b> | <b>Time</b> | <b>Location</b> | <b>Tested by</b>    | <b>Testing Method</b> | <b>Results</b> |
|-----------------------|-------------|-----------------|---------------------|-----------------------|----------------|
| 06/20/2017            | 06:30 AM    | Kitchen S1 #1   | Suburban Labs, Inc. | EPA 200.8             | 21             |
| 06/20/2017            | 06:30 AM    | Kitchen S1 #2   | Suburban Labs, Inc. | EPA 200.8             | 2.09           |
| 06/20/2017            | 06:30 AM    | Kitchen S2 #1   | Suburban Labs, Inc. | EPA 200.8             | 31.3           |
| 06/20/2017            | 06:30 AM    | Kitchen S2 #2   | Suburban Labs, Inc. | EPA 200.8             | 24.4           |

Lynn G Haskin Retest

Faucets were replaced

|            |          |               |                     |           |   |
|------------|----------|---------------|---------------------|-----------|---|
| 08/03/2017 | 05:00 AM | Kitchen S1 #1 | Suburban Labs, Inc. | EPA 200.8 | 0 |
| 08/03/2017 | 05:00 AM | Kitchen S1 #2 | Suburban Labs, Inc. | EPA 200.8 | 0 |
| 08/03/2017 | 05:00 AM | Kitchen S2 #1 | Suburban Labs, Inc. | EPA 200.8 | 0 |
| 08/03/2017 | 05:00 AM | Kitchen S2 #2 | Suburban Labs, Inc. | EPA 200.8 | 0 |